

Polytech CAO - Bug #11345

Connecteur Esp8266-01 a l'envers à corriger !

05/24/2019 04:55 PM - Jacques LAFFONT

Status:	Closed	Start date:	05/24/2019
Priority:	Normal	Due date:	
Assignee:	Francisco SANCHEZ	% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:			
Description			

History

#1 - 05/29/2019 10:59 AM - Jacques LAFFONT

- Status changed from New to Closed

Fait.