

## Cadence\_Pcb\_Librairie - Gantt 2016

#	Tracker	Status	Priority	Subject	Assignee	Updated
2001	Bug	Closed	Normal	probleme empreinte lcd	Jacques LAFFONT	05/21/2013 01:51 PM
1834	Bug	Closed	Normal	erfaire symbole conn_usb_a	Francisco SANCHEZ	01/15/2015 08:11 AM
1799	Bug	Closed	Normal	aligner broches cny version 2 du symbole		05/31/2012 04:50 PM
1767	Bug	Closed	Normal	expliquez comment mettre cleanup dans le projet	Thomas Rousseau	04/28/2015 04:35 PM
1766	Bug	Closed	Normal	ajout wiki url svn	Felix Wasch	06/08/2012 01:50 PM
1765	Bug	Closed	Normal	specification du dossier d'import svn	Francois Jullien	05/24/2012 02:35 PM
1761	Bug	Closed	Normal	Broches port B du composant pic18f4550 non alignées sur la grille	Francisco SANCHEZ	05/31/2012 04:53 PM
1760	Bug	Rejected	Normal	ajouter wiki confusion note signal name	Mohamed Ouameur	04/28/2015 04:35 PM
1754	Bug	Closed	Normal	enlever valeur par defaut capacité	Jacques LAFFONT	05/31/2012 04:55 PM
1753	Bug	Closed	Normal	regarder le contenu de alim 5 15 et supprimer si necessaire	Francisco SANCHEZ	06/01/2012 03:34 PM
1752	Bug	Closed	Normal	verfier commit sur transfo 1 2 (avant et apres)	Francisco SANCHEZ	06/01/2012 03:58 PM
1320	Bug	Closed	Normal	creer cartes breakout pour icd2/icd3		04/28/2015 04:35 PM
1153	Bug	Closed	Normal	Ajouter dans le wiki une explication sur import parmaters si la carte n'a pas été crée correctement		04/28/2015 04:35 PM
1151	Bug	Closed	Normal	ajouter empreintes transistors		06/01/2012 04:02 PM
1150	Bug	Closed	Normal	Aligner broches symbole m32c87 partie alimentation		02/08/2012 09:37 AM
1123	Bug	Closed	Normal	replacer les nom de composants et refdes dans le symbole pcb de la resistance	Francisco SANCHEZ	06/01/2012 04:01 PM
1122	Bug	Rejected	Normal	Ajouter trou de 3mm dans les templates de carte GE A4 1/2 A4 ...	Francisco SANCHEZ	04/28/2015 04:36 PM
1121	Bug	Closed	Normal	Verifier numérotation broches transformateur. Assurer le swap des broches de sorties et verifier le positionnement des broches entre le schema et l'empreinte	Francisco SANCHEZ	02/08/2012 09:32 AM
1102	Bug	Closed	Normal	corriger symbole melf et placer dans une seule librairie	Francisco SANCHEZ	10/14/2011 03:59 PM
1099	Bug	Closed	Normal	Suppression Composant Librayry	Francisco SANCHEZ	10/14/2011 03:59 PM
1096	Bug	Closed	Normal	ameliorer symbole tda2822m	Maxime Forner	10/14/2011 03:58 PM
1095	Bug	Closed	Normal	nettoyer board template	Jacques LAFFONT	10/14/2011 03:58 PM
1093	Bug	Closed	Normal	Projet de sous-traitance	Vincent Garavillon	10/14/2011 04:04 PM
1092	Bug	Closed	Normal	Création de symbole		10/14/2011 04:03 PM
1002	Bug	Closed	Normal	manque boitier dip au max232	Francisco SANCHEZ	10/14/2011 04:01 PM
1001	Bug	Closed	Normal	Probleme Grid MCP4901	Francisco SANCHEZ	09/21/2011 03:36 PM
1000	Bug	Closed	Normal	ajouter un package par defaut au composante bornier 2	Francisco SANCHEZ	10/14/2011 04:04 PM
999	Bug	Closed	Normal	connecteur rs232 thru male (placement sur carte package bound trop grand).	Francisco SANCHEZ	02/08/2012 09:40 AM
998	Bug	Closed	Normal	Probleme Grid Connecteur 10 cms (conn_10_cms)	Francisco SANCHEZ	10/14/2011 04:01 PM
997	Bug	Closed	Normal	Probleme Grid Connecteur usb a	Francisco SANCHEZ	10/14/2011 04:00 PM
996	Bug	Closed	Normal	wiki bien preciser la diffreence entre nom de pga et nom de composants		10/14/2011 04:04 PM
995	Bug	Closed	Normal	empreinte MELF (diode)	Francisco SANCHEZ	10/14/2011 03:57 PM
994	Bug	Closed	Normal	corriger wiki paragraphe 5.3 taille des pistes utiliser plutot les classes		10/14/2011 04:05 PM
977	Bug	Closed	Normal	VOIR LES TROU 2MM5 NE TROUVE PAS LE SOUCIE A VERIFIER LES PACKS	Jacques LAFFONT	06/01/2012 03:59 PM
961	Bug	Closed	Normal	broches connecteur usb b non alignées sur la grille	Francisco SANCHEZ	05/25/2011 02:07 PM
667	Bug	Closed	Normal	sur conn he10 26 pins trou 1 trop petit	Francisco SANCHEZ	05/25/2011 02:09 PM
666	Bug	Closed	Normal	afficheur lcd vérifier les 4 trous de support	Francisco SANCHEZ	05/24/2011 04:32 PM
519	Bug	Closed	Normal	Cacher les numeros de broches sur resistance, condensateurs	Francisco SANCHEZ	05/25/2011 02:34 PM
518	Bug	Closed	Normal	Ajouter swap code sur les transformateurs	Francisco SANCHEZ	05/31/2011 02:27 PM
498	Bug	Closed	Normal	vérifier l'empreinte du lcd " les 4 trous de fixation "	Francisco SANCHEZ	05/24/2011 04:36 PM

#	Tracker	Status	Priority	Subject	Assignee	Updated
493	Bug	Closed	Normal	prop. pack type et pack sur sur point test à diminuer ou effacer		05/24/2011 04:44 PM
492	Bug	Closed	Normal	numerotation broches aff lcd complet à inverser		05/24/2011 04:43 PM
489	Bug	Closed	Normal	agrandir trous du connecteur 17 pins	Francisco SANCHEZ	05/24/2011 04:53 PM
488	Bug	Closed	Normal	refaire empreinte du relais reed 276/1-5-a006	Francisco SANCHEZ	05/25/2011 04:26 PM
448	Bug	Closed	Normal	revision wiki	Jean-Patrick Wanner	05/31/2012 04:55 PM
437	Bug	Closed	Normal	ajouter silk top à c36mm	Francisco SANCHEZ	05/25/2011 05:25 PM
436	Bug	Closed	Normal	enlever shape sur silk top de 4a kbl06	Francisco SANCHEZ	05/25/2011 05:11 PM
418	Bug	Closed	Normal	saisie du composant hxs 20np	Francisco SANCHEZ	10/19/2010 11:17 AM
417	Bug	Closed	Normal	transformateurs verfier primaire secondaires !!!!		05/24/2011 05:02 PM
416	Bug	Closed	Normal	supprimer cadre autour pont de diode		10/20/2010 06:32 PM
415	Feature	Closed	Normal	Ajouter les informations de swap aux composants	Francisco SANCHEZ	05/31/2011 02:24 PM
396	Bug	Closed	Normal	verifier mapping transfo 2 2 1064		10/08/2010 05:25 PM
394	Bug	Closed	Normal	mise a jour des symboles des VCO	Francisco SANCHEZ	10/18/2010 02:41 PM
380	Bug	Closed	Normal	creer bornier 8 et associer empreinte sl508_8		10/08/2010 03:42 PM
379	Bug	Closed	Normal	verfier empreintes capacité polarisée	Francisco SANCHEZ	10/08/2010 03:42 PM
378	Bug	Closed	Normal	creer tl082	Francisco SANCHEZ	10/08/2010 03:43 PM
377	Bug	Closed	Normal	symbole conn usb version 2 avec d- en haut et d+ en bas	Francisco SANCHEZ	10/08/2010 03:43 PM
356	Bug	Closed	Normal	soucie avec les librairies" voir les tag?"	Jacques LAFFONT	10/08/2010 03:43 PM
353	Bug	Closed	Normal	verifier empreinte cav1 couche decalée	Francisco SANCHEZ	10/08/2010 03:44 PM
352	Bug	Closed	Normal	faire l'emprunte de l'aff_lcd sym_2	Francisco SANCHEZ	10/08/2010 03:44 PM
351	Bug	Closed	Normal	alignement broches he20	Hicham Toudghi	10/08/2010 03:44 PM
350	Bug	Closed	Normal	alignement broches he20	Lahoucine Merouhahel	10/08/2010 03:40 PM
348	Bug	Closed	Normal	4a_kbl06 remplacer par symbole pont de diode	Francisco SANCHEZ	10/08/2010 03:41 PM
347	Bug	Closed	Normal	4a_kbl06 broches non alignees		10/08/2010 03:45 PM
332	Bug	Closed	Normal	corriger traco 3 inverser borches	Francisco SANCHEZ	10/08/2010 03:45 PM
331	Bug	Closed	Normal	corriger les afficheurs lcd	Jacques LAFFONT	10/04/2010 03:04 PM
330	Bug	Closed	Normal	corriger symbole conn3	Hicham Toudghi	10/08/2010 03:45 PM
329	Bug	Closed	Normal	unifier les ponts de diode avec gpc3510w	Jacques LAFFONT	10/08/2010 03:45 PM
302	Bug	Closed	Normal	manque empreinte npn	Francisco SANCHEZ	10/08/2010 03:46 PM
296	Bug	Closed	Normal	pas de package pour pont de diode	Francisco SANCHEZ	10/08/2010 03:46 PM
293	Bug	Closed	Normal	symbole pont de diode a refaire	Francisco SANCHEZ	10/08/2010 03:46 PM
289	Bug	Closed	Normal	finaliser symbole relais tyco 1in,v thru	Francisco SANCHEZ	10/08/2010 03:46 PM
288	Bug	Closed	Normal	affectation des broches pour le clavier 12 touches		10/08/2010 03:46 PM
286	Feature	Closed	Normal	ajouter librairies standard (transistor ...) en version minimale pour concept hdl	Jacques LAFFONT	10/08/2010 03:46 PM
282	Bug	Closed	Normal	dans polytech_ge_beta corriger symbole du ltsr6_np	Francisco SANCHEZ	10/08/2010 03:47 PM
281	Feature	Closed	Normal	dans polytech_ge_beta" refaire les bord su symbole du tr36va-18"	Francisco SANCHEZ	10/08/2010 03:47 PM
280	Bug	Closed	Normal	dans polytech_ge_beta"verifier db25 et db25m "	Francisco SANCHEZ	10/08/2010 03:47 PM
279	Bug	Closed	Normal	dans polytech_ge_beta "bp_104 voir empreinte cms"	Francisco SANCHEZ	10/08/2010 03:47 PM
278	Bug	Closed	Normal	dans polytech_ge_beta "aff_lcd manque symbole pour conn16		10/08/2010 03:47 PM
277	Bug	Closed	Normal	verifier cny17-2 et cny17-3	Jacques LAFFONT	10/08/2010 03:40 PM
276	Bug	Closed	Normal	dans polytech_ge_beta "voir symbole adum 1230"		10/08/2010 03:47 PM
275	Feature	Closed	Normal	ajouter empreintes physiques aux transistors npn et pnp générique	Francisco SANCHEZ	10/07/2010 03:46 PM
274	Bug	Closed	Normal	empreinte a faire pour ad2s90	Francisco SANCHEZ	10/08/2010 03:48 PM

#	Tracker	Status	Priority	Subject	Assignee	Updated
273	Bug	Closed	Normal	dans polytech_ge_beta effacer	Francisco SANCHEZ	10/08/2010 03:48 PM
272	Bug	Closed	Normal	faire l'empreinte pour les CNY	Francisco SANCHEZ	10/08/2010 03:48 PM
271	Bug	Closed	Normal	COMMANDE A EFFACER	Francisco SANCHEZ	10/08/2010 03:48 PM
270	Bug	Closed	Normal	ajouter symbole + sur empreint c36mm // verfiier autre capa pol	Francisco SANCHEZ	10/08/2010 03:48 PM
269	Bug	Closed	Normal	transfo vcm, pakstack manquant	Jacques LAFFONT	10/07/2010 03:45 PM
268	Feature	Closed	Normal	Realisation d'une carte de selection d'empreintes	Francisco SANCHEZ	06/01/2011 10:57 AM
267	Feature	Closed	Normal	Regrouper les transistor en générique npn et pnp		10/07/2010 03:43 PM
265	Bug	Closed	Normal	verifier zdm_a1281-a2 et zdm_a1281_b0 si pas les memes	Jacques LAFFONT	10/07/2010 03:46 PM
264	Bug	Closed	Normal	a effacer trans1"vide"	Jacques LAFFONT	10/07/2010 03:46 PM
263	Bug	Closed	Normal	a effacer 4akbl06 "vide"	Jacques LAFFONT	10/07/2010 03:47 PM
262	Bug	Closed	Normal	dans librairie polytech_ge_beta a effacer		10/08/2010 03:49 PM
261	Bug	Closed	Normal	verifier les connecteurs de db9	Francisco SANCHEZ	10/07/2010 03:44 PM
260	Bug	Closed	Normal	verifier c_220nf_400v avec c 22nf_400		10/08/2010 03:49 PM
258	Bug	Closed	Normal	verifier location a <<null>> pour zener mib ge	Jacques LAFFONT	09/20/2010 09:12 AM
257	Bug	Closed	Normal	2N2219 manque location, symbole a refaire	Francisco SANCHEZ	10/08/2010 03:49 PM
256	Bug	Closed	Normal	configuration des artworks non opérationnellement	Jacques LAFFONT	10/18/2010 02:13 PM
255	Bug	Closed	Normal	Capacite C220NF_400V a fusionner avec capacite et supprimer		10/07/2010 03:43 PM
254	Bug	Closed	Normal	package npn lib ge		10/08/2010 03:49 PM
253	Bug	Closed	Normal	Traiter connecter fjack alim	Francisco SANCHEZ	10/08/2010 03:49 PM
214	Bug	Closed	Normal	taille empreinte capacitee 100n		10/07/2010 03:39 PM
203	Bug	Closed	Normal	EMPREINTE TRANSISTOR	Jacques LAFFONT	09/15/2010 10:10 PM
202	Bug	Closed	Normal	Empreinte Jack Femelle		10/08/2010 03:50 PM
190	Bug	Closed	Normal	borche alignement	Jacques LAFFONT	09/15/2010 10:09 PM